

VESSEL:	GSF RIG 140	CLIENT:	EBH Namibia		
JOB No.:	SP 1115	DATE:	31-01-2011	PAGE:	1



JOB	Items	Description
AB 401	11	Seawater piping
AB 010	12	Helideck drains and gutter repairs on accommodation
AB 017		Moon pool Walkway
AB 402		Flare boom well test piping STB / AFT
AB 018		AFT Crane panels
AB 024		Mud logging radiator platform
AB 016		Elmagco Winch Break STB Pontoon
AB 033		Shaker house ducting
AB 035		Anchor bolster repairs
AB 403		10" overboard line STB side
AB 028		Bolster camera supports
AB 037		STB crane panels
AB 039		Anchor Repairs
AB 040		Ducting for electrical motor over rotary table
AB 041		Supply and fit grating to columns
AB 046		Insulation in Port & Starboard pontoon



Seawater Piping

- Low Pressure air compressor salt water stainless steel lines.
- Main engine cooling supply & return lines.
- Renew air compressor 4" stainless steel salt water supply & return line
- Renew 2" and 6" additional seawater lines in engine room
- Fabricate and install additional 3" pipes to HP compressor
- Renew 6" drill water line in Caisson 2 S
- Renew draw works salt and cooling water supply & return lines
- Water maker salt water supply and return lines
- 12" Bend renewal in port pontoon pump room
- Weld 12" flanges to sea water line in port pump room
- Draw works 2" pipe



Helideck

Gutter repairs at accommodation
Port & Starboard heli-deck drain lines
Removal of existing gutters & grating, replace with new gutters
Repair on Moon Pool Walkway
Flare Boom Well Test Piping
Aft Crane Panel



Radiator Platform
Almaco Winch Break Modification
Shaker House Ducting
10" Overboard Pipe
Starboard Crane Panels
Anchor Repairs
Ducting for Electric Motor to Rotary Table
Refit Grating on Column Platform

